

PowerPro™ 5600 Portable Charger USER MANUAL Model PP-56

Thank you for purchasing the LUNA™ state-of-the-art PowerPro™ 5600 Portable Charger, with 5600 mAh of on-the-go mega power. Many portable chargers give you only a few extra hours of use before they are depleted. However, the LUNA PowerPro™ will fully charge most smart phones three times before it has to be re-charged.

- This manual explains the basic steps involved in charging and using your LUNA PowerPro™ portable charger.
- Read this manual carefully before use.

Please remove product components from the case and confirm that you have the following items:

- 1 LUNA PowerPro™ Portable Charger
- 1 USB to Micro-USB Cable

PowerPro™ Components

- 1 Input
- 2 Output
- 3 LED Flashlight
- 4 Power Button
- 5 Power Indicator Lights



Input: Charging the PowerPro™

Before charging the LUNA PowerPro™, press the Power Button 4 to determine the level of available power.

Power Indicator	One Light On	Two Lights On	Three Lights On	Four Lights On
Power of PowerPro™	<25%	25-50%	50-75%	75-100%

To charge the LUNA **PowerPro™**, plug the USB Connector on the Charging Cable into a power supply using a USB AC adapter, computer USB port, or a car charger with USB connectivity.



USB AC ADAPTER



COMPUTER USB PORT



Plug the Micro-USB Connector on the Charging Cable into the Input Port ① on the LUNA PowerPro™ and continue charging until no Power Indicator Lights ⑤ are blinking. A blinking light indicates that the LUNA PowerPro™ is being charged. For instance, if two lights are on, and a third light is blinking, it means the LUNA PowerPro™ is more than 50% charged, but less than 75% charged. Four non-blinking Power Indicator Lights indicates the LUNA PowerPro™ is fully charged. Fully charging the LUNA PowerPro™ can take 5-6 hours.

Output: Charging Your Devices

Charging Cable Compatibility

To charge a mobile phone, MP3 player, tablet PC, or other device that has a Micro-USB input port, the LUNA PowerPro™ Charging Cable may be used to charge the device. If your device has a different type of power input port, you will need a USB charging cable that is compatible with your device to be able to use the LUNA PowerPro™. In recent years, most AC chargers sold with mobile phones and tablet PCs (including Apple) have USB functionality, so please check your existing AC adapter for USB functionality before buying a USB charging cable for your device.

Charging

Simply plug in your USB charging cable into the Output Port 2 on the LUNA PowerPro™ and connect to your device. Press the Power Button 4 and charging will begin immediately. The Power Indicator Lights 5 will remain on until your device is fully charged.

Specifications

Capacity: 5600 mAh Dimension: 3.7"/93mm (L) x 1.7"/43mm (W) x 0.8"/22mm (H)

Input: DC 5V/1A Weight: 4.3 oz/123.5g

Input Charging Time: 5-6 hours Charging Cable Connectors: USB and Micro-USB

Output: DC 5.3V/1A Charging Cable Length: 24"/60cm

LED Flashlight

The LUNA PowerPro™ is equipped with a handy LED Flashlight ③ that can be turned "on" or "off" by pressing the Power Button ④ twice. The LED Flashlight will illuminate for approximately 250 hours before the LUNA PowerPro™ has to be re-charged.

Warranty & Returns

LUNA International, LLC (LUNA™) agrees to repair or replace without cost any LUNA PowerPro™ which, under normal and intended use, has proven to be defective in material or workmanship within one (1) year from the date of original purchase. Returned packages will only be accepted with a pre-authorized RMA number written on the outside of the package. An RMA number can be obtained via the LUNA™ website at: www.LunaTechUSA.com. The shipping costs of the returned items to LUNA™ shall be the sole responsibility of the purchaser. Proof of purchase is required.

LUNA™ is not responsible or liable for any mishandling, neglect or damage arising from improper use of the LUNA PowerPro™. Any modification to the product shall make the warranty offered herein null and void, thereby relieving LUNA™ from any and all responsibility or liability.

Caution

Do not use the LUNA PowerPro[™] outdoors in inclement weather or expose it to wet or damp conditions. Do not leave in a location exposed to direct sunlight or near a heater. Do not drop the LUNA PowerPro[™] on a hard surface or into a liquid. Do not disassemble. Storage temperature: –4°F to +140°F (–20°C to +60°C).



www.lunatechusa.com

Copyright © LUNA International, LLC - Tampa, Florida • 813.260.2630 All products mentioned are trademarks or registered trademarks of their respective owners.

MADE IN CHINA Rev. 2.1